

ADVISORY NOTE

| | | |
|---|-----------------------------|----------------|
| Date of issue | 29 th March 2023 | |
| Note number | ND_2303_04 | |
| Product name and catalogue numer | Name | Cat. No |
| | Liquick Cor-FERRUM 30 | 3-257 |
| | Liquick Cor-FERRUM 60 | 3-258 |
| | Liquick Cor-FERRUM 120 | 3-334 |
| Lot number | all lots | |
| Expiry date | n/a | |
| Issue description | | |
| <p>Results obtained during routine reagent quality control exceeded the internal acceptance criteria. The values assigned for iron in:</p> <ul style="list-style-type: none"> - CORMAY SERUM HN (Cat. No 5-172) – lot HN10, - CORMAY SERUM HP (Cat. No 5-173) – lot HP10 <p>were re-determined for the manual method and reported in the erratum NDE_2303_03 (Appendix 1).</p> | | |
| Necessary actions | | |
| <ul style="list-style-type: none"> • Read carefully the Advisory Note and erratum NDE_2303_03 and use the re-determined values of controls during determinations of iron. • Perform quality control prior to ordering patient samples. • Please complete and return the verification form. <p>The note is only for reference. Do not discard the product!</p> | | |

Please provide this information to all Users of the above product and keep the Advisory Note as a quality system documentation.

Please complete and return the attached Verification Form to confirm receipt of the Advisory Note.

We apologize for any inconvenience caused by the above situation.

Sincerely,

Quality Assurance Coordinator